

**ROSE CREEK WATERSHED ASSESSMENT OPPORTUNITIES  
BIOLOGICAL RESOURCES  
TECHNICAL MEMORANDUM**

*Prepared for:*

*San Diego Earthworks*  
PO Box 9827  
San Diego, CA 92169

*Prepared by:*

*Merkel & Associates, Inc.*  
5434 Ruffin Road  
San Diego, CA 92123

**May 2005**

# TABLE OF CONTENTS

<b>INTRODUCTION .....</b>	<b>1</b>
<b>METHODS .....</b>	<b>3</b>
<b>RESULTS .....</b>	<b>4</b>
VEGETATION COMMUNITIES AND WILDLIFE HABITATS.....	4
BIOLOGICAL MANAGEMENT ISSUES.....	8
<i>Habitat Fragmentation</i> .....	8
Adverse Edge Effects .....	9
Tenuous Habitat Linkages and Movement Corridors.....	10
Wildlife Mortality at Movement Corridors.....	11
<i>Habitat Degradation</i> .....	13
Narrowing Riparian Zones.....	13
<i>Invasive Species Infestations</i> .....	13
Invasive Plants.....	13
Hottentot Fig.....	18
Pampas Grass.....	18
Giant Reed.....	19
Brazilian Pepper.....	19
Eucalyptus.....	19
Invasive Animals.....	20
Argentine Ant.....	20
African Clawed-frog.....	20
Bullfrog.....	21
Brown-headed Cowbird.....	21
Black Rat.....	22
House Mouse.....	22
Feral Domestic Cat.....	22
Virginia Opossum.....	23
<i>Transient Encampments</i> .....	23
<b>BIOLOGICAL RECOMMENDATIONS FOR WATERSHED IMPROVEMENTS .....</b>	<b>24</b>
<b>LITERATURE CITED.....</b>	<b>27</b>

**LIST OF TABLES**

**Table 1.** Vegetation Communities within the Study Area ..... 5  
**Table 2.** List of the most common invasive plant species in Rose Creek Watershed..... 15  
**Table 3.** List of the most common invasive animal species in Rose Creek Watershed..... 20  
**Table 4.** Recommendations for Ecological Improvements in the Rose Creek Watershed..... 25

**LIST OF FIGURES**

Figure 1. Focus regions of the Rose Creek Watershed ..... 2  
Figure 2a. Rose Creek Watershed Vegetation and Wildlife Habitats (Northern Section)..... 6  
Figure 2b. Rose Creek Watershed Vegetation and Wildlife Habitats (Southern Section)..... 7  
Figure 3. Habitat link between Carroll Canyon and Rose Creek. Red arrows show the relative strength of connections..... 10  
Figure 4. Vertical walled concrete channel of Rose Creek at East Mission Bay Drive..... 11  
Figure 5. Fencing along the southern edge of Miramar Road and urban development along Eastgate Mall Road serve to funnel wildlife onto as many as eight lanes of traffic with high speed off ramps of I-805..... 12  
Figure 6. Area of high mammal mortality; view of Miramar Road facing west with a view of the intersection with Nobel Drive..... 12  
Figure 7. Channel incision..... 13  
Figure 8. Stream bank erosion..... 13  
Figure 9. Effects of Channel Incision on Riparian Habitats ..... 12  
Figure 10a. Rose Creek Watershed Invasive Plant Distribution (Northern Section)..... 16  
Figure 10b. Rose Creek Watershed Invasive Plant Distribution (Southern Section)..... 17  
Figure 11. Hottentot fig dominates slopes below neighborhoods within the lower watershed..... 18  
Figure 12. Pampas grass often form dense patches..... 18  
Figure 13. Argentine ants are most common in areas of moist substrate ..... 20  
Figure 14. Adult African clawed-frogs rarely leave the water of quiet perennial pools ..... 21  
Figure 15. The bullfrog is closely associated with perennial pools ..... 21  
Figure 16. Domestic cat preying on a song bird..... 22  
Figure 17. A transient encampment located in the lower Rose Creek in the vicinity of East Mission Bay Drive overpass..... 23